



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3619

Date: 15-12-2025

## PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

|                            |                                    |
|----------------------------|------------------------------------|
| Insurer Details:           | UNITED INDIA INSURANCE COMPANY LTD |
| Name of Proposer:          | RISHI KESH                         |
| Date & Time of Inspection: | 15/12/2025 AT 11:46 AM             |
| Location of Vehicle:       |                                    |

### Vehicle Particulars:

|                        |                        |             |             |
|------------------------|------------------------|-------------|-------------|
| Vehicle Regd No:       | RJ34 RB 9268           | Chassis No: | 09122       |
| Make/Model:            | MAHINDRA SWARAJ<br>841 | Engine No:  | A0236       |
| Date of Regd/Purchase: | 15/03/2024             | Mileage:    | NOT WORKING |

### Inspection/Parts Details:

|                  |          |                   |          |
|------------------|----------|-------------------|----------|
| Roof             | Intact   | Bonnetfrt Show    | Intact   |
| Front Bumper     | Intact   | Lh Door           | --None-- |
| Rh Door          | --None-- | Lh Side Body      | Intact   |
| Rh Side Body     | Intact   | Lh Fender         | Intact   |
| Rh Fender        | Intact   | Lh Qtr Panel      | --None-- |
| Rh Qtr Panel     | --None-- | Frt Ws Glass      | --None-- |
| Lh Qtr Glass     | --None-- | Rh Qtr Glass      | --None-- |
| Lh Head Lamp     | Intact   | Rh Head Lamp      | Intact   |
| Lh Tail Lamp     | Intact   | Rh Tail Lamp      | Intact   |
| Tyres            | Average  | Wheel Rim         | Intact   |
| Rear View Mirror | --None-- | Dash Boardlpanel  | Intact   |
| Frt Grille       | Intact   | Type Of Load Body | Open     |

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

|                            |     |          |  |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: |  |
|----------------------------|-----|----------|--|



  
Arvind Gaur  
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Captured by Timestamp Camera  
#Timestamp Camera  
15/12/2025 11:44 AM GMT+05:30  
Kodiya, Rajasthan, India  
26.68483°N, 76.87051°E  
Timestamp camera



Captured by Timestamp Camera  
#Timestamp Camera  
15/12/2025 11:46 AM GMT+05:30  
Kodiya, Rajasthan, India  
26.68484°N, 76.87054°E  
Timestamp camera



Captured by Timestamp Camera  
#Timestamp Camera  
15/12/2025 11:35 AM GMT+05:30  
Kodiya, Rajasthan, India  
26.68476°N, 76.87046°E  
Timestamp camera



Captured by Timestamp Camera  
#Timestamp Camera  
15/12/2025 11:35 AM GMT+05:30  
Kodiya, Rajasthan, India  
26.68477°N, 76.87048°E  
Timestamp camera



Captured by Timestamp Camera  
#Timestamp Camera  
15/12/2025 11:36 AM GMT+05:30  
Kodiya, Rajasthan, India  
26.68479°N, 76.87048°E  
Timestamp camera



Captured by Timestamp Camera  
#Timestamp Camera  
15/12/2025 11:51 AM GMT+05:30  
Kodiya, Rajasthan, India  
26.68478°N, 76.87052°E  
Timestamp camera



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory