



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1005

Date: 26-07-2025

## PRE -INSPECTION REPORT- FOUR WHEELER

Insurer Details:	UIIC
Name of Proposer:	MR. MANGAL SINGH
Date & Time of Inspection:	26/07/2025 AT 11:19 AM
Location of Vehicle:	BAARI

### Vehicle Particulars:

Vehicle Regd No:	RJ11 UA 2155	Chassis No:	00070
Make/Model:	HONDA MOBILIO 1.5	Engine No:	07126
Date of Regd/Purchase:	27/11/2014	Mileage:	50366 KM

### Inspection/Parts Details:

Roof	Intact	Bonnet	Intact
Lh Fender	Dent	Rh Fender	Intact
Lh Frt Door	Intact	Rh Frt Door	Intact
Lh Rear Door	Intact	Rh Rear Door	Intact
Lh Qtr Panel	Intact	Rh Qtr Panel	Intact
Lh Side Body	Intact	Rh Side Body	Intact
Lh Running Board	Intact	Rh Running Board	Intact
Dicky	Intact	Front Bumper	Intact
Rear Bumper	Intact	Frt Ws Glass	Intact
Dicky Glass	Intact	Lh Mirror	Intact
Rh Mirror	Intact	Lh Head Lamp	Intact
Rh Head Lamp	Intact	Tail Lamps	Intact
Tyre Wheel	Average	Dash Board I Panel	Intact

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	LH RUNNING BORD DENT
----------------------------	-----	----------	----------------------



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



नाम-रहित सड़क, बारी, राजस्थान 328021, भारत,  
अक्षांश: 26.641664, लंबा: 77.630015  
26 जुल, 25, 11:18 am, शनिवार

34.35° 116 द पू



नाम-रहित सड़क, बारी, राजस्थान 328021, भारत,  
अक्षांश: 26.641595, लंबा: 77.629965  
26 जुल, 25, 11:16 am, शनिवार

34.35° 206 द पू



नाम-रहित सड़क, बारी, राजस्थान 328021, भारत,  
अक्षांश: 26.641560, लंबा: 77.630014  
26 जुल, 25, 11:17 am, शनिवार

34.35° 289 प



नाम-रहित सड़क, बारी, राजस्थान  
328021, भारत,  
अक्षांश: 26.641654, लंबा: 77.629993  
26 जुल, 25, 11:18 am, शनिवार

34.35° 106 पू



नाम-रहित सड़क, बारी, राजस्थान 328021, भारत,  
अक्षांश: 26.641641, लंबा: 77.630007  
26 जुल, 25, 11:19 am, शनिवार


34.35° 23 उ पू



नाम-रहित सड़क, बारी, राजस्थान  
328021, भारत,  
अक्षांश: 26.641535, लंबा: 77.630124  
26 जुल, 25, 11:17 am, शनिवार

34.35° 320 उ पू



  
Arvind Gaur  
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)