# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1035 Date: 28-07-2025

**PRE -INSPECTION REPORT- FOUR WHEELER**

| | |
|---|---|
| Insurer Details: | UNITED INDIA INSURANCE CO. LTD |
| Name of Proposer: | MR. RAVI KUMAR BHAND |
| Date & Time of Inspection: | 28/07/2025 AT 04:27 PM |
| Location of Vehicle: | GAJSINGHPUR JAIPUR |

**Vehicle Particulars:**

| | | | |
|---|---|---|---|
| Vehicle Regd No: | RJ25 CA 8701 | Chassis No: | 68016 |
| Make/Model: | MARUTI EECO | Engine No: | 70148 |
| Date of Regd/Purchase: | 24/11/2020 | Mileage: | 61503 KM |

**Inspection/Parts Details:**

| | | | |
|---|---|---|---|
| Roof | Intact | Bonnet | Intact |
| Lh Fender | Intact | Rh Fender | Intact |
| Lh Frt Door | Intact | Rh Frt Door | Intact |
| Lh Rear Door | Intact | Rh Rear Door | Intact |
| Lh Qtr Panel | Intact | Rh Qtr Panel | Intact |
| Lh Side Body | Intact | Rh Side Body | Intact |
| Lh Running Board | Intact | Rh Running Board | Intact |
| Dicky | Dent | Front Bumper | Intact |
| Rear Bumper | Intact | Frt Ws Glass | Intact |
| Dicky Glass | Intact | Lh Mirror | Intact |
| Rh Mirror | Intact | Lh Head Lamp | Intact |
| Rh Head Lamp | Intact | Tail Lamps | Intact |
| Tyre Wheel | Average | Dash Board I Panel | Intact |

**Note:** - Pre Existing Damages are not covered in the Insurance.Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|---|---|---|---|
| Recommended For Insurance: | Yes | Remarks: | |

Click here to verify

Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

*73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)*

# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Click here to verify

Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

*73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)*