



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1194

Date: 07-08-2025

PRE -INSPECTION REPORT- TWO WHEELER

Insurer Details:	UII
Name of Proposer:	MR KAILASH CHAND JAGARWAL
Date & Time of Inspection:	07/08/2005 AT 12:30 PM
Location of Vehicle:	CHAKSU JAIPUR

Vehicle Particulars:

Vehicle Regd No:	RJ14 ND 2272	Chassis No:	F81201
Make/Model:	HERO PASSION PRO	Engine No:	F10380
Date of Regd/Purchase:	17/09/2015	Mileage:	76498 KM

Inspection/Parts Details:

Frt Mud Guard	Intact	Fork	Intact
Handle	Intact	Speedometer	Intact
Fuel Tank	Intact	Rear Mud Guard	Intact
Silencer	Intact	Crank Case	Intact
Seats	Intact	Leg Guard	Intact
Front Wheel Rim	Intact	Rear Wheel Rim	Intact
Head Lamp	Intact	Tail Lamp	Intact
Front Visor Cowl	Intact	Front Rh Indicator	Intact
Front Lh Indicator	Intact	Rear Rh Indicator	Intact
Rear Lh Indicator	Intact	Rh Side Cover	Intact
Lh Side Cover	Intact	Clutch Lever	Intact
Brake Lever	Intact	Tyre	Average
Lh Mirror	Intact	Rh Mirror	Intact

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Chaksu Rajasthan Aug 7, 2025, 12:30



Chaksu Rajasthan Aug 7, 2025, 12:30



Chaksu Rajasthan Aug 7, 2025, 12:31



Chaksu Rajasthan Aug 7, 2025, 12:30



Chaksu Rajasthan Aug 7, 2025, 12:30



Chaksu Rajasthan Aug 7, 2025, 12:30



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory