



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1206

Date: 07-08-2025

## PRE -INSPECTION REPORT- FOUR WHEELER

|                            |                        |
|----------------------------|------------------------|
| Insurer Details:           | UII                    |
| Name of Proposer:          | MR SUKHRAM JAT         |
| Date & Time of Inspection: | 07/08/2025 AT 03:02 PM |
| Location of Vehicle:       | JOBNER, JAIPUR         |

### Vehicle Particulars:

|                        |                    |             |           |
|------------------------|--------------------|-------------|-----------|
| Vehicle Regd No:       | RJ14 CV 9547       | Chassis No: | M089599   |
| Make/Model:            | HYUNDAI GRAND I-10 | Engine No:  | M096728   |
| Date of Regd/Purchase: | 18/04/2014         | Mileage:    | 141477 KM |

### Inspection/Parts Details:

|                  |         |                    |         |
|------------------|---------|--------------------|---------|
| Roof             | Intact  | Bonnet             | Dent    |
| Lh Fender        | Dent    | Rh Fender          | Intact  |
| Lh Frt Door      | Intact  | Rh Frt Door        | Intact  |
| Lh Rear Door     | Intact  | Rh Rear Door       | Intact  |
| Lh Qtr Panel     | Intact  | Rh Qtr Panel       | Intact  |
| Lh Side Body     | Intact  | Rh Side Body       | Intact  |
| Lh Running Board | Intact  | Rh Running Board   | Intact  |
| Dicky            | Intact  | Front Bumper       | Screwed |
| Rear Bumper      | Scratch | Frt Ws Glass       | Intact  |
| Dicky Glass      | Intact  | Lh Mirror          | Intact  |
| Rh Mirror        | Intact  | Lh Head Lamp       | Intact  |
| Rh Head Lamp     | Intact  | Tail Lamps         | Intact  |
| Tyre Wheel       | Average | Dash Board I Panel | Intact  |

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

|                            |     |          |             |
|----------------------------|-----|----------|-------------|
| Recommended For Insurance: | Yes | Remarks: | RC VERIFIED |
|----------------------------|-----|----------|-------------|



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Aug 7, 2025 15:02:15  
25.6626,971061666666667N 75.38071E  
Jobner  
Jaipur Division  
Rajasthan  
Altitude:364.3msnm  
Speed:0.0km/h  
Index number: 484



Aug 7, 2025 15:04:03  
26.971061666666667N 75.38071E  
Jobner  
Jaipur Division  
Rajasthan  
Altitude:364.3msnm  
Speed:0.0km/h  
Index number: 488



Aug 7, 2025 15:00:17  
26.971021666666667N 75.38062333333333E  
Jobner  
Jaipur Division  
Rajasthan  
Altitude:354.0msnm  
Speed:0.8km/h  
Index number: 465



Aug 7, 2025 15:00:33  
26.971076666666665N 75.38074E  
Jobner  
Jaipur Division  
Rajasthan  
Altitude:363.8msnm  
Speed:2.9km/h  
Index number: 469



Aug 7, 2025 15:00:25  
26.971068333333333N 75.380685E  
Jobner  
Jaipur Division  
Rajasthan  
Altitude:363.5msnm  
Speed:2.0km/h  
Index number: 467



Aug 7, 2025 15:00:44  
26.971040000000002N 75.38071333333333E  
Jobner  
Jaipur Division  
Rajasthan  
Altitude:363.5msnm  
Speed:1.8km/h  
Index number: 471



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory