



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1455

Date: 21-08-2025

PRE -INSPECTION REPORT- FOUR WHEELER

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	MR. DIYAL
Date & Time of Inspection:	21/08/2025 AT 08:36 AM
Location of Vehicle:	MORER AJMER

Vehicle Particulars:

Vehicle Regd No:	RJ21 UC 4494	Chassis No:	18291
Make/Model:	MAHINDRA SCORPIO S11	Engine No:	15659
Date of Regd/Purchase:	13/01/2022	Mileage:	102750 KM

Inspection/Parts Details:

Roof	Intact	Bonnet	Intact
Lh Fender	Intact	Rh Fender	Intact
Lh Frt Door	Intact	Rh Frt Door	Intact
Lh Rear Door	Intact	Rh Rear Door	Intact
Lh Qtr Panel	Intact	Rh Qtr Panel	Intact
Lh Side Body	Intact	Rh Side Body	Intact
Lh Running Board	Intact	Rh Running Board	Intact
Dicky	Intact	Front Bumper	Intact
Rear Bumper	Intact	Frt Ws Glass	Intact
Dicky Glass	Intact	Lh Mirror	Intact
Rh Mirror	Intact	Lh Head Lamp	Intact
Rh Head Lamp	Intact	Tail Lamps	Intact
Tyre Wheel	Average	Dash Board I Panel	Intact

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Arvind Gaur
Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)