



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1469

Date: 22-08-2025

PRE -INSPECTION REPORT- FOUR WHEELER

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	MR. UTAM SINGH
Date & Time of Inspection:	22/08/2025 AT 09:53 AM
Location of Vehicle:	JODHPUR

Vehicle Particulars:

Vehicle Regd No:	RJ39 CA 6169	Chassis No:	68853
Make/Model:	MARUTI SWIFT DZIRE VDI	Engine No:	63911
Date of Regd/Purchase:	23/02/2013	Mileage:	143236 KM

Inspection/Parts Details:

Roof	Intact	Bonnet	Intact
Lh Fender	Dent	Rh Fender	Intact
Lh Frt Door	Dent	Rh Frt Door	Intact
Lh Rear Door	Intact	Rh Rear Door	Intact
Lh Qtr Panel	Intact	Rh Qtr Panel	Intact
Lh Side Body	Intact	Rh Side Body	Intact
Lh Running Board	Intact	Rh Running Board	Intact
Dicky	Intact	Front Bumper	Intact
Rear Bumper	Screwed	Frt Ws Glass	Broken
Dicky Glass	Intact	Lh Mirror	Intact
Rh Mirror	Intact	Lh Head Lamp	Intact
Rh Head Lamp	Intact	Tail Lamps	Intact
Tyre Wheel	Average	Dash Board I Panel	Intact

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



22 अग° 2025 9:51:37 am
कनखी - बालीतरा - सयाला मार्ग
पादरू
जोधपुर डिवीजन
राजस्थान



22 अग° 2025 9:51:24 am
कनखी - बालीतरा - सयाला मार्ग
पादरू
जोधपुर डिवीजन
राजस्थान



22 अग° 2025 9:51:13 am
कनखी - बालीतरा - सयाला मार्ग
पादरू
जोधपुर डिवीजन
राजस्थान



22 अग° 2025 9:50:58 am
इत्वाया
जोधपुर डिवीजन
राजस्थान



22 अग° 2025 9:53:59 am
कनखी - बालीतरा - सयाला मार्ग
पादरू
जोधपुर डिवीजन
राजस्थान



22 अग° 2025 9:54:36 am
कनखी - बालीतरा - सयाला मार्ग
पादरू
जोधपुर डिवीजन
राजस्थान



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory