



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1553

Date: 26-08-2025

PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	MR. NARENDER KUMAR
Date & Time of Inspection:	26/08/2025 AT 04:55 PM
Location of Vehicle:	MURLIPURA JAIPUR

Vehicle Particulars:

Vehicle Regd No:	HR26 DG 5045	Chassis No:	34190
Make/Model:	ACTION CONSTRUCTION EQUIPMENT 14XW	Engine No:	91742
Date of Regd/Purchase:	12/09/2017	Mileage:	NOTWORKING

Inspection/Parts Details:

Roof	Intact	Bonnetfrt Show	Intact
Front Bumper	Intact	Lh Door	Intact
Rh Door	Intact	Lh Side Body	Intact
Rh Side Body	Intact	Lh Fender	--None--
Rh Fender	--None--	Lh Qtr Panel	--None--
Rh Qtr Panel	--None--	Frt Ws Glass	Intact
Lh Qtr Glass	Intact	Rh Qtr Glass	Intact
Lh Head Lamp	Intact	Rh Head Lamp	Intact
Lh Tail Lamp	Intact	Rh Tail Lamp	Intact
Tyres	Average	Wheel Rim	Intact
Rear View Mirror	Intact	Dash Boardlpanel	Intact
Frt Grille	Intact	Type Of Load Body	Open

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Aug 26, 2025 4:54:49 PM



Aug 26, 2025 4:55:50 PM



Aug 26, 2025 4:55:35 PM



Aug 26, 2025 4:36:02 PM



Aug 26, 2025 4:54:32 PM



Aug 26, 2025 4:54:11 PM



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory