



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1561

Date: 27-08-2025

PRE -INSPECTION REPORT- FOUR WHEELER

| | |
|----------------------------|--------------------------------|
| Insurer Details: | UNITED INDIA INSURANCE CO. LTD |
| Name of Proposer: | M/S OM SERVICES |
| Date & Time of Inspection: | 27/08/2025 AT 07:43 AM |
| Location of Vehicle: | JODHPUR |

Vehicle Particulars:

| | | | |
|------------------------|---------------------------|-------------|----------|
| Vehicle Regd No: | UP 32 RN 3694 | Chassis No: | 91944 |
| Make/Model: | MAHINDRA BOLERO CAMPER | Engine No: | 88830 |
| Date of Regd/Purchase: | 30/07/2022 | Mileage: | 95049 KM |

Inspection/Parts Details:

| | | | |
|------------------|---------|--------------------|--------|
| Roof | Intact | Bonnet | Intact |
| Lh Fender | Intact | Rh Fender | Intact |
| Lh Frt Door | Intact | Rh Frt Door | Intact |
| Lh Rear Door | Intact | Rh Rear Door | Intact |
| Lh Qtr Panel | Intact | Rh Qtr Panel | Intact |
| Lh Side Body | Intact | Rh Side Body | Intact |
| Lh Running Board | Intact | Rh Running Board | Intact |
| Dicky | Intact | Front Bumper | Intact |
| Rear Bumper | Intact | Frt Ws Glass | Intact |
| Dicky Glass | Intact | Lh Mirror | Intact |
| Rh Mirror | Intact | Lh Head Lamp | Intact |
| Rh Head Lamp | Intact | Tail Lamps | Intact |
| Tyre Wheel | Average | Dash Board I Panel | Intact |

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: | |
|----------------------------|-----|----------|--|



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



27 अग° 2025 07:42:48
नाम-रहित सड़क
मुन्जसर
जोधपुर डिवीजन
राजस्थान



27 अग° 2025 07:43:05
बर्जसर
जोधपुर डिवीजन
राजस्थान



27 अग° 2025 07:42:04
नाम-रहित सड़क
मुन्जसर
जोधपुर डिवीजन
राजस्थान



27 अग° 2025 07:41:09
मुन्जसर
जोधपुर डिवीजन
राजस्थान



27 अग° 2025 07:40:34
बर्जसर
जोधपुर डिवीजन
राजस्थान



27 अग° 2025 08:01:01
बर्जसर
जोधपुर डिवीजन
राजस्थान




Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)