



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1596

Date: 28-08-2025

PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	M/S PRATAP CONSTRUCTION
Date & Time of Inspection:	28/08/2025 AT 10:10 AM
Location of Vehicle:	MAKRANA

Vehicle Particulars:

Vehicle Regd No:	RJ37 EA 1508	Chassis No:	39559
Make/Model:	MAHINDRA BOLERO PICK UP	Engine No:	31427
Date of Regd/Purchase:	25/06/2024	Mileage:	8441 KM

Inspection/Parts Details:

Roof	Intact	Bonnetfrt Show	Intact
Front Bumper	Intact	Lh Door	Intact
Rh Door	Intact	Lh Side Body	Intact
Rh Side Body	Intact	Lh Fender	Intact
Rh Fender	Intact	Lh Qtr Panel	Intact
Rh Qtr Panel	Intact	Frt Ws Glass	Intact
Lh Qtr Glass	Intact	Rh Qtr Glass	Intact
Lh Head Lamp	Intact	Rh Head Lamp	Intact
Lh Tail Lamp	Intact	Rh Tail Lamp	Intact
Tyres	Average	Wheel Rim	Intact
Rear View Mirror	Intact	Dash Boardlpanel	Intact
Frt Grille	Intact	Type Of Load Body	--None--

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	VEHICLE FITTEED WITH RIG
----------------------------	-----	----------	--------------------------



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

Arvind Gaur
Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory