



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1643

Date: 31-08-2025

PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

| | |
|----------------------------|----------------------------------|
| Insurer Details: | THE NEW INDIA ASSURANCE CO. LTD. |
| Name of Proposer: | MR AMITAV DAS |
| Date & Time of Inspection: | 31/08/2025 AT 01:37 PM |
| Location of Vehicle: | LOONIYAWAS, JAIPUR |

Vehicle Particulars:

| | | | |
|------------------------|------------------------------|-------------|-----------------------|
| Vehicle Regd No: | A/F | Chassis No: | MB1PREHD2SART366 9 |
| Make/Model: | ASHOK LEYLAND TF 2012 BUS | Engine No: | SRPZ102543 |
| Date of Regd/Purchase: | 21/02/2025 | Mileage: | 180 |

Inspection/Parts Details:

| | | | |
|------------------|---------|-------------------|--------|
| Roof | Intact | Bonnetfrt Show | Intact |
| Front Bumper | Intact | Lh Door | Intact |
| Rh Door | Intact | Lh Side Body | Intact |
| Rh Side Body | Intact | Lh Fender | Intact |
| Rh Fender | Intact | Lh Qtr Panel | Intact |
| Rh Qtr Panel | Intact | Frt Ws Glass | Intact |
| Lh Qtr Glass | Intact | Rh Qtr Glass | Intact |
| Lh Head Lamp | Intact | Rh Head Lamp | Intact |
| Lh Tail Lamp | Intact | Rh Tail Lamp | Intact |
| Tyres | Average | Wheel Rim | Intact |
| Rear View Mirror | Intact | Dash Boardlpanel | Intact |
| Frt Grille | Intact | Type Of Load Body | Closed |

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|----------------------------|-----|----------|-------------|
| Recommended For Insurance: | Yes | Remarks: | NEW VEHICLE |
|----------------------------|-----|----------|-------------|



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)