



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1648

Date: 30-08-2025

PRE -INSPECTION REPORT- FOUR WHEELER

| | |
|----------------------------|------------------------|
| Insurer Details: | UIIC |
| Name of Proposer: | SURGYAN |
| Date & Time of Inspection: | 30/08/2025 AT 02:00 PM |
| Location of Vehicle: | MAKRANA, NAGAUR |

Vehicle Particulars:

| | | | |
|------------------------|-----------------------|-------------|-------------|
| Vehicle Regd No: | RJ48 CA 1221 | Chassis No: | E25074 |
| Make/Model: | MARUTI WAGON R VXI | Engine No: | 012667 |
| Date of Regd/Purchase: | 08/08/2018 | Mileage: | NOT WORKING |

Inspection/Parts Details:

| | | | |
|------------------|---------|--------------------|--------|
| Roof | Intact | Bonnet | Intact |
| Lh Fender | Intact | Rh Fender | Intact |
| Lh Frt Door | Intact | Rh Frt Door | Intact |
| Lh Rear Door | Intact | Rh Rear Door | Intact |
| Lh Qtr Panel | Intact | Rh Qtr Panel | Intact |
| Lh Side Body | Intact | Rh Side Body | Intact |
| Lh Running Board | Intact | Rh Running Board | Intact |
| Dicky | Intact | Front Bumper | Intact |
| Rear Bumper | Broken | Frt Ws Glass | Intact |
| Dicky Glass | Intact | Lh Mirror | Intact |
| Rh Mirror | Intact | Lh Head Lamp | Intact |
| Rh Head Lamp | Intact | Tail Lamps | Intact |
| Tyre Wheel | Average | Dash Board I Panel | Intact |

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|----------------------------|-----|----------|-------------|
| Recommended For Insurance: | Yes | Remarks: | RC VERIFIED |
|----------------------------|-----|----------|-------------|



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)




Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Aug 30, 2025 1:59:05 PM
Manglana Road
Deawali Colony
Makrana
Ajmer Division
Rajasthan



Aug 30, 2025 2:00:45 PM
Manglana Road
Deawali Colony
Makrana
Ajmer Division
Rajasthan



Aug 30, 2025 1:59:34 PM
Manglana Road
Deawali Colony
Makrana
Ajmer Division
Rajasthan



Aug 30, 2025 1:59:55 PM
Manglana Road
Deawali Colony
Makrana
Ajmer Division
Rajasthan



Aug 30, 2025 1:59:13 PM
Manglana Road
Deawali Colony
Makrana
Ajmer Division
Rajasthan



Aug 30, 2025 1:58:46 PM
Manglana Road
Deawali Colony
Makrana
Ajmer Division
Rajasthan



Arvind Gaur
Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)