



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1666

Date: 01-09-2025

## PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

|                            |                                |
|----------------------------|--------------------------------|
| Insurer Details:           | UNITED INDIA INSURANCE CO. LTD |
| Name of Proposer:          | MR. AKIL AHMED                 |
| Date & Time of Inspection: | 01/09/2025 AT 04:03 PM         |
| Location of Vehicle:       | KOTA                           |

### Vehicle Particulars:

|                        |                        |             |          |
|------------------------|------------------------|-------------|----------|
| Vehicle Regd No:       | RJ20 PA 8557           | Chassis No: | 78529    |
| Make/Model:            | PIAGGIO AP AUTO<br>D3S | Engine No:  | 33679    |
| Date of Regd/Purchase: | 22/05/2015             | Mileage:    | 80615 KM |

### Inspection/Parts Details:

|                  |         |                   |          |
|------------------|---------|-------------------|----------|
| Roof             | Intact  | Bonnetfrt Show    | Intact   |
| Front Bumper     | Intact  | Lh Door           | Intact   |
| Rh Door          | Intact  | Lh Side Body      | Intact   |
| Rh Side Body     | Intact  | Lh Fender         | Intact   |
| Rh Fender        | Intact  | Lh Qtr Panel      | Intact   |
| Rh Qtr Panel     | Intact  | Frt Ws Glass      | Intact   |
| Lh Qtr Glass     | Intact  | Rh Qtr Glass      | Intact   |
| Lh Head Lamp     | Intact  | Rh Head Lamp      | Intact   |
| Lh Tail Lamp     | Intact  | Rh Tail Lamp      | Intact   |
| Tyres            | Average | Wheel Rim         | Intact   |
| Rear View Mirror | Intact  | Dash Boardlpanel  | Intact   |
| Frt Grille       | Intact  | Type Of Load Body | --None-- |

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

|                            |     |          |  |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: |  |
|----------------------------|-----|----------|--|



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



1 Sept 2025 16:03:50  
Station Main Road  
Bhimganj Mandi  
Kota Division  
Rajasthan



1 Sept 2025 16:02:32  
Bhimganj Mandi  
Kota Division  
Rajasthan



1 Sept 2025 16:03:28  
Bhimganj Mandi  
Kota Division  
Rajasthan



1 Sept 2025 16:03:01  
Bhimganj Mandi  
Kota Division  
Rajasthan



1 Sept 2025 16:03:13  
Bhimganj Mandi  
Kota Division  
Rajasthan



1 Sept 2025 16:04:13  
Bhimganj Mandi  
Kota Division  
Rajasthan



  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)