



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1705

Date: 03-09-2025

PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	M/S SHRI BALAJI CORPORATION COMPANY
Date & Time of Inspection:	03/09/2025 AT 02:45 PM
Location of Vehicle:	KORADI MAHARASHTRA

Vehicle Particulars:

Vehicle Regd No:	VIN 0541	Chassis No:	00541
Make/Model:	HYDRAULIC TWIN BOOM JUMBO	Engine No:	
Date of Regd/Purchase:	2024	Mileage:	NOTWORKING

Inspection/Parts Details:

Roof	Intact	Bonnetfrt Show	Intact
Front Bumper	Intact	Lh Door	Intact
Rh Door	Intact	Lh Side Body	Intact
Rh Side Body	Intact	Lh Fender	Intact
Rh Fender	Intact	Lh Qtr Panel	Intact
Rh Qtr Panel	Intact	Frt Ws Glass	Intact
Lh Qtr Glass	Intact	Rh Qtr Glass	Intact
Lh Head Lamp	Intact	Rh Head Lamp	Intact
Lh Tail Lamp	Intact	Rh Tail Lamp	Intact
Tyres	Average	Wheel Rim	Intact
Rear View Mirror	Intact	Dash Boardlpanel	Intact
Frt Grille	Intact	Type Of Load Body	--None--

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--




Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

Arvind Gaur
 Arvind Gaur
 Surveyor & Loss Assessor

Authorized Signatory