



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1759

Date: 08-09-2025

## PRE -INSPECTION REPORT- FOUR WHEELER

|                            |                                |
|----------------------------|--------------------------------|
| Insurer Details:           | UNITED INDIA INSURANCE CO. LTD |
| Name of Proposer:          | MR. BHAIRU RAM                 |
| Date & Time of Inspection: | 08/09/2025 AT 12:23 PM         |
| Location of Vehicle:       | BAGRU JAIPUR                   |

### Vehicle Particulars:

|                        |                       |             |           |
|------------------------|-----------------------|-------------|-----------|
| Vehicle Regd No:       | RJ45 CX 9117          | Chassis No: | 06473     |
| Make/Model:            | MARUTI SWIFT<br>DZIRE | Engine No:  | 53478     |
| Date of Regd/Purchase: | 2015                  | Mileage:    | 170962 KM |

### Inspection/Parts Details:

|                  |         |                    |        |
|------------------|---------|--------------------|--------|
| Roof             | Intact  | Bonnet             | Intact |
| Lh Fender        | Intact  | Rh Fender          | Intact |
| Lh Frt Door      | Intact  | Rh Frt Door        | Intact |
| Lh Rear Door     | Intact  | Rh Rear Door       | Intact |
| Lh Qtr Panel     | Intact  | Rh Qtr Panel       | Intact |
| Lh Side Body     | Intact  | Rh Side Body       | Intact |
| Lh Running Board | Intact  | Rh Running Board   | Intact |
| Dicky            | Intact  | Front Bumper       | Intact |
| Rear Bumper      | Intact  | Frt Ws Glass       | Intact |
| Dicky Glass      | Intact  | Lh Mirror          | Intact |
| Rh Mirror        | Intact  | Lh Head Lamp       | Intact |
| Rh Head Lamp     | Intact  | Tail Lamps         | Intact |
| Tyre Wheel       | Average | Dash Board I Panel | Intact |

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

|                            |     |          |  |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: |  |
|----------------------------|-----|----------|--|



  
Arvind Gaur  
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Sep 8, 2025 12:23:02 PM  
Link Road  
Bagru  
Jaipur Division  
Rajasthan



Sep 8, 2025 12:22:47 PM  
Link Road  
Bagru  
Jaipur Division  
Rajasthan



Sep 8, 2025 12:23:15 PM  
Link Road  
Bagru  
Jaipur Division  
Rajasthan



Sep 8, 2025 12:23:53 PM  
Link Road  
Bagru  
Jaipur Division  
Rajasthan



Sep 8, 2025 12:22:08 PM  
Link Road  
Bagru  
Jaipur Division  
Rajasthan



Sep 8, 2025 12:22:33 PM  
Link Road  
Bagru  
Jaipur Division  
Rajasthan



  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)