



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1778

Date: 08-09-2025

PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

| | |
|----------------------------|--------------------------------|
| Insurer Details: | UNITED INDIA INSURANCE CO. LTD |
| Name of Proposer: | MR. BODU SINGH |
| Date & Time of Inspection: | 08/09/2025 AT 03:46 PM |
| Location of Vehicle: | MAKRANA |

Vehicle Particulars:

| | | | |
|------------------------|---------------|-------------|-----------|
| Vehicle Regd No: | RJ32 GA 8047 | Chassis No: | 17727 |
| Make/Model: | TATA LPT 1109 | Engine No: | 21186 |
| Date of Regd/Purchase: | 03/05/2011 | Mileage: | 395860 KM |

Inspection/Parts Details:


| | | | |
|------------------|---------|-------------------|----------|
| Roof | Intact | Bonnetfrt Show | Intact |
| Front Bumper | Intact | Lh Door | Intact |
| Rh Door | Intact | Lh Side Body | Intact |
| Rh Side Body | Intact | Lh Fender | Intact |
| Rh Fender | Intact | Lh Qtr Panel | Intact |
| Rh Qtr Panel | Intact | Frt Ws Glass | Intact |
| Lh Qtr Glass | Intact | Rh Qtr Glass | Intact |
| Lh Head Lamp | Intact | Rh Head Lamp | Intact |
| Lh Tail Lamp | Intact | Rh Tail Lamp | Intact |
| Tyres | Average | Wheel Rim | Intact |
| Rear View Mirror | Intact | Dash Boardlpanel | Intact |
| Frt Grille | Intact | Type Of Load Body | --None-- |

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: | |
|----------------------------|-----|----------|--|



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Sep 8, 2025 3:40:53 PM
Makrana
Ajmer Division
Rajasthan



Sep 8, 2025 3:46:42 PM
Makrana
Ajmer Division
Rajasthan



Sep 8, 2025 3:35:49 PM
Makrana
Ajmer Division
Rajasthan



Sep 8, 2025 3:38:55 PM
Makrana
Ajmer Division
Rajasthan



Sep 8, 2025 3:36:14 PM
Makrana
Ajmer Division
Rajasthan



Sep 8, 2025 3:35:09 PM
Manglana Road,
Deawali Colony
Makrana
Ajmer Division
Rajasthan



Arvind Gaur
Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)