



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1780

Date: 09-09-2025

## PRE -INSPECTION REPORT- FOUR WHEELER

|                            |                        |
|----------------------------|------------------------|
| Insurer Details:           | NIA                    |
| Name of Proposer:          | MR. RAJ KUMAR SAINI    |
| Date & Time of Inspection: | 09/09/2025 AT 09:10 AM |
| Location of Vehicle:       | MADHORAJPURA, JAIPUR   |

### Vehicle Particulars:

|                        |                        |             |        |
|------------------------|------------------------|-------------|--------|
| Vehicle Regd No:       | RJ34 CA 2089           | Chassis No: | 926019 |
| Make/Model:            | MARUTI ALTO 800<br>LXI | Engine No:  | 586933 |
| Date of Regd/Purchase: | 06/10/2016             | Mileage:    | 60782  |

### Inspection/Parts Details:

|                  |         |                    |         |
|------------------|---------|--------------------|---------|
| Roof             | Intact  | Bonnet             | Intact  |
| Lh Fender        | Intact  | Rh Fender          | Intact  |
| Lh Frt Door      | Dent    | Rh Frt Door        | Intact  |
| Lh Rear Door     | Intact  | Rh Rear Door       | Scratch |
| Lh Qtr Panel     | Intact  | Rh Qtr Panel       | Intact  |
| Lh Side Body     | Intact  | Rh Side Body       | Intact  |
| Lh Running Board | Dent    | Rh Running Board   | Dent    |
| Dicky            | Intact  | Front Bumper       | Intact  |
| Rear Bumper      | Intact  | Frt Ws Glass       | Intact  |
| Dicky Glass      | Intact  | Lh Mirror          | Intact  |
| Rh Mirror        | Intact  | Lh Head Lamp       | Intact  |
| Rh Head Lamp     | Intact  | Tail Lamps         | Intact  |
| Tyre Wheel       | Average | Dash Board I Panel | Intact  |

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

|                            |     |          |            |
|----------------------------|-----|----------|------------|
| Recommended For Insurance: | Yes | Remarks: | RC VERFIED |
|----------------------------|-----|----------|------------|



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Sep 9, 2025 9:02:38 AM  
Phagi - Chaksu Road  
Madhorajpura  
Jaipur Division  
Rajasthan



Sep 9, 2025 9:02:57 AM  
Phagi - Chaksu Road  
Madhorajpura  
Jaipur Division  
Rajasthan




Sep 9, 2025 9:04:24 AM  
Madhorajpura  
Jaipur Division  
Rajasthan



Sep 9, 2025 9:05:03 AM



Sep 9, 2025 9:05:40 AM  
Madhorajpura  
Jaipur Division  
Rajasthan



Sep 9, 2025 9:06:10 AM  
Madhorajpura  
Jaipur Division  
Rajasthan



  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)