



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1803

Date: 10-09-2025

PRE -INSPECTION REPORT- TWO WHEELER

| | |
|----------------------------|--------------------------------|
| Insurer Details: | UNITED INDIA INSURANCE CO. LTD |
| Name of Proposer: | MR. RAMKARN CHOUDHARY |
| Date & Time of Inspection: | 10/09/2025 AT 07:19 AM |
| Location of Vehicle: | BHAOSINGHPURA JAIPUR |

Vehicle Particulars:

| | | | |
|------------------------|----------------|-------------|----------|
| Vehicle Regd No: | RJ14 XJ 1518 | Chassis No: | 01580 |
| Make/Model: | HERO HF DELUXE | Engine No: | 01930 |
| Date of Regd/Purchase: | 21/09/2020 | Mileage: | 74871 KM |

Inspection/Parts Details:

| | | | |
|--------------------|--------|--------------------|---------|
| Frt Mud Guard | Intact | Fork | Intact |
| Handle | Intact | Speedometer | Intact |
| Fuel Tank | Intact | Rear Mud Guard | Intact |
| Silencer | Intact | Crank Case | Intact |
| Seats | Intact | Leg Guard | Intact |
| Front Wheel Rim | Intact | Rear Wheel Rim | Intact |
| Head Lamp | Intact | Tail Lamp | Intact |
| Front Visor Cowl | Intact | Front Rh Indicator | Intact |
| Front Lh Indicator | Intact | Rear Rh Indicator | Intact |
| Rear Lh Indicator | Intact | Rh Side Cover | Intact |
| Lh Side Cover | Intact | Clutch Lever | Intact |
| Brake Lever | Intact | Tyre | Average |
| Lh Mirror | Intact | Rh Mirror | Intact |

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: | |
|----------------------------|-----|----------|--|



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



10 Sept 2025 07:26:53
Dahmi Kalan
Jaipur Division
Rajasthan



10 Sept 2025 07:19:18
Ghegha Road
Garedo Ki Dhani
Bhaosinghpura
Jaipur Division
Rajasthan



10 Sept 2025 07:18:26
Ghegha Road
Garedo Ki Dhani
Bhaosinghpura
Jaipur Division
Rajasthan



10 Sept 2025 07:18:12
Ghegha Road
Garedo Ki Dhani
Bhaosinghpura
Jaipur Division
Rajasthan



10 Sept 2025 07:17:43
Dahmi Kalan
Jaipur Division
Rajasthan



10 Sept 2025 07:13:14
Ghegha Road
Garedo Ki Dhani
Bhaosinghpura
Jaipur Division
Rajasthan



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory