



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1878

Date: 12-09-2025

PRE -INSPECTION REPORT- FOUR WHEELER

| | |
|----------------------------|--------------------------------|
| Insurer Details: | UNITED INDIA INSURANCE CO. LTD |
| Name of Proposer: | MR. HANSRAJ SAINI |
| Date & Time of Inspection: | 12/09/2025 AT 12:36 PM |
| Location of Vehicle: | NIWARU ROAD JAIPUR |

Vehicle Particulars:

| | | | |
|------------------------|-----------------------|-------------|-----------|
| Vehicle Regd No: | RJ14 LC 4797 | Chassis No: | 84214 |
| Make/Model: | MARUTI SWIFT DZIRE | Engine No: | 51880 |
| Date of Regd/Purchase: | 08/02/2016 | Mileage: | 220976 KM |

Inspection/Parts Details:

| | | | |
|------------------|---------|--------------------|--------|
| Roof | Intact | Bonnet | Intact |
| Lh Fender | Intact | Rh Fender | Intact |
| Lh Frt Door | Intact | Rh Frt Door | Intact |
| Lh Rear Door | Intact | Rh Rear Door | Intact |
| Lh Qtr Panel | Intact | Rh Qtr Panel | Intact |
| Lh Side Body | Intact | Rh Side Body | Intact |
| Lh Running Board | Intact | Rh Running Board | Intact |
| Dicky | Intact | Front Bumper | Intact |
| Rear Bumper | Intact | Frt Ws Glass | Intact |
| Dicky Glass | Intact | Lh Mirror | Intact |
| Rh Mirror | Intact | Lh Head Lamp | Intact |
| Rh Head Lamp | Intact | Tail Lamps | Intact |
| Tyre Wheel | Average | Dash Board I Panel | Intact |

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: | |
|----------------------------|-----|----------|--|



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



12 Sept 2025 12:34:18 pm
10 Niwaru Road
Nangal Jaisabohra
Jaipur Division
Rajasthan



12 Sept 2025 12:36:05 pm
10 Niwaru Road
Nangal Jaisabohra
Jaipur Division
Rajasthan



12 Sept 2025 12:33:00 pm
10 Niwaru Road
Nangal Jaisabohra
Jaipur Division
Rajasthan



12 Sept 2025 12:32:05 pm
10 Niwaru Road
Nangal Jaisabohra
Jaipur Division
Rajasthan



12 Sept 2025 12:31:53 pm
10 Niwaru Road
Nangal Jaisabohra
Jaipur Division
Rajasthan



12 Sept 2025 12:31:34 pm
10 Niwaru Road
Nangal Jaisabohra
Jaipur Division
Rajasthan



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory