



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 1988

Date: 19-09-2025

PRE -INSPECTION REPORT- TWO WHEELER

| | |
|----------------------------|--------------------------------|
| Insurer Details: | UNITED INDIA INSURANCE CO. LTD |
| Name of Proposer: | ARUN BANJARA |
| Date & Time of Inspection: | 19/09/2025 AT 11:16 AM |
| Location of Vehicle: | BIJOLIA |

Vehicle Particulars:

| | | | |
|------------------------|----------------|-------------|----------|
| Vehicle Regd No: | RJ06 WS 2846 | Chassis No: | 02523 |
| Make/Model: | HERO HF DELUXE | Engine No: | 05002 |
| Date of Regd/Purchase: | 25/02/2019 | Mileage: | 22642 KM |

Inspection/Parts Details:

| | | | |
|--------------------|--------|--------------------|---------|
| Frt Mud Guard | Intact | Fork | Intact |
| Handle | Intact | Speedometer | Intact |
| Fuel Tank | Intact | Rear Mud Guard | Intact |
| Silencer | Intact | Crank Case | Intact |
| Seats | Intact | Leg Guard | Intact |
| Front Wheel Rim | Intact | Rear Wheel Rim | Intact |
| Head Lamp | Intact | Tail Lamp | Intact |
| Front Visor Cowl | Intact | Front Rh Indicator | Intact |
| Front Lh Indicator | Intact | Rear Rh Indicator | Intact |
| Rear Lh Indicator | Intact | Rh Side Cover | Intact |
| Lh Side Cover | Intact | Clutch Lever | Intact |
| Brake Lever | Intact | Tyre | Average |
| Lh Mirror | Intact | Rh Mirror | Intact |

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: | |
|----------------------------|-----|----------|--|




Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Sep 19, 2025 11:18:03 AM
25.14724891N 75.3321672E
Govindpura
Udaipur Division
Rajasthan



Sep 19, 2025 11:16:46 AM
25.14723248N 75.33204623E
Govindpura
Udaipur Division
Rajasthan



Sep 19, 2025 11:16:30 AM
25.14723198N 75.33204572E
Govindpura
Udaipur Division
Rajasthan



Sep 19, 2025 11:16:13 AM
25.14723597N 75.3320367E
National Highway 27
Choraha
Bijolia
Udaipur Division
Rajasthan



Sep 19, 2025 11:15:56 AM
25.14726042N 75.33203111E
National Highway 27
Choraha
Bijolia
Udaipur Division
Rajasthan



Sep 19, 2025 11:15:50 AM
25.14723356N 75.33193765E
National Highway 27
Choraha
Bijolia
Udaipur Division
Rajasthan



Arvind Gaur
Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)