



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 2097

Date: 24-09-2025

## PRE -INSPECTION REPORT- TWO WHEELER

|                            |                                |
|----------------------------|--------------------------------|
| Insurer Details:           | UNITED INDIA INSURANCE CO. LTD |
| Name of Proposer:          | MISS SEETA DEVI                |
| Date & Time of Inspection: | 24/09/2025 AT 03:48 PM         |
| Location of Vehicle:       | CHAKSU JAIPUR                  |

### Vehicle Particulars:

|                        |                |             |            |
|------------------------|----------------|-------------|------------|
| Vehicle Regd No:       | RJ14JY 3829    | Chassis No: | 13288      |
| Make/Model:            | HONDA CB SHINE | Engine No:  | 28155      |
| Date of Regd/Purchase: | 2019           | Mileage:    | NOTWORKING |

### Inspection/Parts Details:

|                    |        |                    |         |
|--------------------|--------|--------------------|---------|
| Frt Mud Guard      | Intact | Fork               | Intact  |
| Handle             | Intact | Speedometer        | Intact  |
| Fuel Tank          | Intact | Rear Mud Guard     | Intact  |
| Silencer           | Intact | Crank Case         | Intact  |
| Seats              | Intact | Leg Guard          | Intact  |
| Front Wheel Rim    | Intact | Rear Wheel Rim     | Intact  |
| Head Lamp          | Intact | Tail Lamp          | Intact  |
| Front Visor Cowl   | Intact | Front Rh Indicator | Intact  |
| Front Lh Indicator | Intact | Rear Rh Indicator  | Intact  |
| Rear Lh Indicator  | Intact | Rh Side Cover      | Intact  |
| Lh Side Cover      | Intact | Clutch Lever       | Intact  |
| Brake Lever        | Intact | Tyre               | Average |
| Lh Mirror          | Intact | Rh Mirror          | Intact  |

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

|                            |     |          |  |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: |  |
|----------------------------|-----|----------|--|



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



24 Sept 2025 3:48:58 pm  
Chaksu  
Jaipur Division  
Rajasthan



24 Sept 2025 3:47:32 pm  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



24 Sept 2025 3:48:07 pm  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



24 Sept 2025 3:47:22 pm  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



24 Sept 2025 3:46:34 pm  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



24 Sept 2025 3:47:27 pm  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory