



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 2154

Date: 26-09-2025

## PRE -INSPECTION REPORT- TWO WHEELER

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	MR. CHOUTH MAL GURJAR
Date & Time of Inspection:	26/09/2025 AT 01:19 PM
Location of Vehicle:	CHAKSU JAIPUR

### Vehicle Particulars:

Vehicle Regd No:	RJ14 NH 1490	Chassis No:	00031
Make/Model:	HERO SPLENDOR+	Engine No:	00008
Date of Regd/Purchase:	22/01/2018	Mileage:	96485 KM

### Inspection/Parts Details:

Frt Mud Guard	Broken	Fork	Intact
Handle	Intact	Speedometer	Intact
Fuel Tank	Dent	Rear Mud Guard	Intact
Silencer	Intact	Crank Case	Intact
Seats	Intact	Leg Guard	Intact
Front Wheel Rim	Intact	Rear Wheel Rim	Intact
Head Lamp	Intact	Tail Lamp	Intact
Front Visor Cowl	Broken	Front Rh Indicator	Intact
Front Lh Indicator	Intact	Rear Rh Indicator	Intact
Rear Lh Indicator	Intact	Rh Side Cover	Intact
Lh Side Cover	Intact	Clutch Lever	Intact
Brake Lever	Intact	Tyre	Average
Lh Mirror	Intact	Rh Mirror	Intact

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--



  
Arvind Gaur  
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



26 Sept 2025 1:19:20 pm  
72° E  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



26 Sept 2025 1:19:24 pm  
159° S  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



26 Sept 2025 1:19:18 pm  
103° E  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



26 Sept 2025 1:19:10 pm  
345° N  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



26 Sept 2025 1:19:00 pm  
318° NW  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



26 Sept 2025 1:18:51 pm  
245° SW  
Chaksu Road  
Chaksu  
Jaipur Division  
Rajasthan



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory