



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 2217

Date: 30-09-2025

## PRE -INSPECTION REPORT- FOUR WHEELER

Insurer Details:	THE NEW INDIA ASSURANCE CO. LTD
Name of Proposer:	MR. PRAHLAD RAI YADAV
Date & Time of Inspection:	30/09/2025 AT 01:45 PM
Location of Vehicle:	BHAINSAWA

### Vehicle Particulars:

Vehicle Regd No:	RJ41 CA 6289	Chassis No:	07573
Make/Model:	MARUTI VITARA BREZZA ZDI	Engine No:	79699
Date of Regd/Purchase:	05/02/2020	Mileage:	58910 KM

### Inspection/Parts Details:

Roof	Intact	Bonnet	Intact
Lh Fender	Intact	Rh Fender	Intact
Lh Frt Door	Intact	Rh Frt Door	Intact
Lh Rear Door	Intact	Rh Rear Door	Intact
Lh Qtr Panel	Intact	Rh Qtr Panel	Intact
Lh Side Body	Intact	Rh Side Body	Intact
Lh Running Board	Intact	Rh Running Board	Intact
Dicky	Intact	Front Bumper	Intact
Rear Bumper	Intact	Frt Ws Glass	Intact
Dicky Glass	Intact	Lh Mirror	Intact
Rh Mirror	Intact	Lh Head Lamp	Intact
Rh Head Lamp	Intact	Tail Lamps	Intact
Tyre Wheel	Average	Dash Board I Panel	Intact

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor


Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



2025-09-30 13:46  
27.0935483, 75.5020283  
36V3+F3, Bhainsawa, Rajasthan 303123, India



2025-09-30 13:43  
27.0936683, 75.5021867  
3+F3, Bhainsawa, Rajasthan 303123, India



2025-09-30 13:43  
27.093715, 75.502215  
36V3+F3, Bhainsawa, Rajasthan 303123, India



2025-09-30 13:45  
27.0936683, 75.5022067  
36V3+F3, Bhainsawa, Rajasthan 303123, India



2025-09-30 13:44  
27.0936067, 75.5021867  
36V3+F3, Bhainsawa, Rajasthan 303123, India



2025-09-30 13:43  
27.0936117, 75.5021867  
3+F3, Bhainsawa, Rajasthan 303123, India



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory