



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 2244

Date: 01-10-2025

PRE -INSPECTION REPORT- TWO WHEELER

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	MR. RONAK YADAV
Date & Time of Inspection:	01/10/2025 AT 03:26 PM
Location of Vehicle:	NEEMRANA

Vehicle Particulars:

Vehicle Regd No:	RJ02 KB 6912	Chassis No:	02829
Make/Model:	YAMAHA MT 15	Engine No:	77833
Date of Regd/Purchase:	05/06/2023	Mileage:	13491 KM

Inspection/Parts Details:

Frt Mud Guard	Intact	Fork	Intact
Handle	Intact	Speedometer	Intact
Fuel Tank	Intact	Rear Mud Guard	Intact
Silencer	Intact	Crank Case	Intact
Seats	Intact	Leg Guard	Intact
Front Wheel Rim	Intact	Rear Wheel Rim	Intact
Head Lamp	Intact	Tail Lamp	Intact
Front Visor Cowl	Intact	Front Rh Indicator	Intact
Front Lh Indicator	Intact	Rear Rh Indicator	Intact
Rear Lh Indicator	Intact	Rh Side Cover	Intact
Lh Side Cover	Intact	Clutch Lever	Intact
Brake Lever	Intact	Tyre	Average
Lh Mirror	Intact	Rh Mirror	Intact

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur


Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Captured by Timestamp Camera
#Timestamp Camera
01/10/2025 03:25:18 GMT+05:30
Neemrana,Kotputli Behror,Rajasthan,India
27.960153°N, 76.348193°E
Timestamp Camera



Captured by Timestamp Camera
#Timestamp Camera
01/10/2025 03:25:27 GMT+05:30
Neemrana,Kotputli Behror,Rajasthan,India
27.960153°N, 76.348193°E
Timestamp Camera




Captured by Timestamp Camera
#Timestamp Camera
01/10/2025 03:27:08 GMT+05:30
Neemrana,Kotputli Behror,Rajasthan,India
27.960153°N, 76.348193°E
Timestamp Camera



Captured by Timestamp Camera
#Timestamp Camera
01/10/2025 03:24:46 GMT+05:30
Neemrana,Kotputli Behror,Rajasthan,India
27.960153°N, 76.348193°E
Timestamp Camera



Captured by Timestamp Camera
#Timestamp Camera
01/10/2025 03:25:49 GMT+05:30
Neemrana,Kotputli Behror,Rajasthan,India
27.960153°N, 76.348193°E
Timestamp Camera



Captured by Timestamp Camera
#Timestamp Camera
01/10/2025 03:25:49 GMT+05:30
Neemrana,Kotputli Behror,Rajasthan,India
27.960153°N, 76.348193°E
Timestamp Camera



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory