



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3045

Date: 13-11-2025

## PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

Insurer Details:	UIIC
Name of Proposer:	MR BAJRANG LAL BAIRWA
Date & Time of Inspection:	13/11/2025 AT 03:40 PM
Location of Vehicle:	BHANKROTA, JAIPUR

### Vehicle Particulars:

Vehicle Regd No:	RJ29 PA 2554	Chassis No:	C03263
Make/Model:	TATA LP 407 BUS	Engine No:	612288
Date of Regd/Purchase:	16/07/2018	Mileage:	NOT WORKING

### Inspection/Parts Details:

Roof	Intact	Bonnetfrt Show	Intact
Front Bumper	Broken	Lh Door	Intact
Rh Door	Intact	Lh Side Body	Intact
Rh Side Body	Intact	Lh Fender	Intact
Rh Fender	Intact	Lh Qtr Panel	Intact
Rh Qtr Panel	Intact	Frt Ws Glass	Intact
Lh Qtr Glass	Intact	Rh Qtr Glass	Intact
Lh Head Lamp	Intact	Rh Head Lamp	Intact
Lh Tail Lamp	Intact	Rh Tail Lamp	Intact
Tyres	Average	Wheel Rim	Intact
Rear View Mirror	Intact	Dash Boardlpanel	Intact
Frt Grille	Intact	Type Of Load Body	Closed

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	RC VERIFIED
----------------------------	-----	----------	-------------



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Nov 13, 2025 3:40:41 PM  
11/A/28A Ring Road  
Bhakraota  
Jaipur Division  
Rajasthan



Nov 13, 2025 3:46:41 PM  
Bhakraota  
Jaipur Division  
Rajasthan



Nov 13, 2025 3:40:58 PM  
11/A/07 RING ROAD  
Bhakraota  
Jaipur Division  
Rajasthan



Nov 13, 2025 3:39:31 PM  
11/A/28A Ring Road  
Bhakraota  
Jaipur Division  
Rajasthan



Nov 13, 2025 3:39:03 PM  
11/A/28A Ring Road  
Bhakraota  
Jaipur Division  
Rajasthan



Nov 13, 2025 3:39:21 PM  
11/A/28A Ring Road  
Bhakraota  
Jaipur Division  
Rajasthan



*Arvind Gaur*  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)