



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3076

Date: 15-11-2025

PRE -INSPECTION REPORT- FOUR WHEELER

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	TULSI RAM
Date & Time of Inspection:	15/11/2025 AT 10:11 AM
Location of Vehicle:	BAGRU JAIPUR

Vehicle Particulars:

Vehicle Regd No:	RJ14 CK 1965	Chassis No:	13160
Make/Model:	CHEVROLET BEAT	Engine No:	85KC3
Date of Regd/Purchase:	27/07/2010	Mileage:	126656 KM

Inspection/Parts Details:

Roof	Intact	Bonnet	Intact
Lh Fender	Intact	Rh Fender	Intact
Lh Frt Door	Intact	Rh Frt Door	Intact
Lh Rear Door	Intact	Rh Rear Door	Intact
Lh Qtr Panel	Intact	Rh Qtr Panel	Dent
Lh Side Body	Intact	Rh Side Body	Intact
Lh Running Board	Intact	Rh Running Board	Intact
Dicky	Intact	Front Bumper	Screwed
Rear Bumper	Screwed	Frt Ws Glass	Intact
Dicky Glass	Intact	Lh Mirror	Intact
Rh Mirror	Intact	Lh Head Lamp	Intact
Rh Head Lamp	Intact	Tail Lamps	Intact
Tyre Wheel	Average	Dash Board I Panel	Intact

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--




Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Nov 15, 2025 9:58:44 AM
26.82545959N 75.54487736E
RGFV+XX4, Ghegha, Bagru, Rajasthan 303007, India



Nov 15, 2025 9:59:15 AM
26.82545907N 75.54483356E
RGFV+XX4, Ghegha, Bagru, Rajasthan 303007, India



Nov 15, 2025 9:59:01 AM
26.82542754N 75.54486332E
RGFV+XX4, Ghegha, Bagru, Rajasthan 303007, India



Nov 15, 2025 9:58:28 AM
26.82548454N 75.54483916E
RGFV+XX4, Ghegha, Bagru, Rajasthan 303007, India



Nov 15, 2025 10:01:12 AM
26.82546752N 75.54485757E
RGFV+XX4, Ghegha, Bagru, Rajasthan 303007, India



Nov 15, 2025 10:02:05 AM
26.82545923N 75.54484402E
RGFV+XX4, Ghegha, Bagru, Rajasthan 303007, India



Arvind Gaur
Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)