



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3179

Date: 20-11-2025

## PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	BALAJI DAYAL PURA INFRA PVT LTD
Date & Time of Inspection:	20/11/2025 AT 08:00 AM
Location of Vehicle:	BHAWANI PURA

### Vehicle Particulars:

Vehicle Regd No:	RJ19 GK 7733	Chassis No:	X2143
Make/Model:	ASHOK LEYLAND UJ 3525/52	Engine No:	24304
Date of Regd/Purchase:	17/11/2023	Mileage:	64687 KM

### Inspection/Parts Details:

Roof	Intact	Bonnetfrt Show	Intact
Front Bumper	Intact	Lh Door	Intact
Rh Door	Intact	Lh Side Body	Intact
Rh Side Body	Intact	Lh Fender	Intact
Rh Fender	Intact	Lh Qtr Panel	Intact
Rh Qtr Panel	Intact	Frt Ws Glass	Intact
Lh Qtr Glass	Intact	Rh Qtr Glass	Intact
Lh Head Lamp	Intact	Rh Head Lamp	Intact
Lh Tail Lamp	Intact	Rh Tail Lamp	Intact
Tyres	Average	Wheel Rim	Intact
Rear View Mirror	Intact	Dash Boardlpanel	Intact
Frt Grille	Intact	Type Of Load Body	--None--

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

*Arvind Gaur*  
 Arvind Gaur  
 Surveyor & Loss Assessor

Authorized Signatory