



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3220

Date: 21-11-2025

## PRE -INSPECTION REPORT- FOUR WHEELER

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	MR. PREM NARAIN VERMA
Date & Time of Inspection:	21/11/2025 AT 02:31 PM
Location of Vehicle:	VIDYADHAR NAGAR JAIPUR

### Vehicle Particulars:

Vehicle Regd No:	RJ14 WC 7562	Chassis No:	33649
Make/Model:	MARUTI WAGON R VXI	Engine No:	65456
Date of Regd/Purchase:	07/06/2017	Mileage:	83697 KM

### Inspection/Parts Details:

Roof	Intact	Bonnet	Intact
Lh Fender	Intact	Rh Fender	Intact
Lh Frt Door	Intact	Rh Frt Door	Intact
Lh Rear Door	Intact	Rh Rear Door	Intact
Lh Qtr Panel	Intact	Rh Qtr Panel	Intact
Lh Side Body	Intact	Rh Side Body	Intact
Lh Running Board	Intact	Rh Running Board	Intact
Dicky	Intact	Front Bumper	Intact
Rear Bumper	Intact	Frt Ws Glass	Intact
Dicky Glass	Intact	Lh Mirror	Intact
Rh Mirror	Intact	Lh Head Lamp	Intact
Rh Head Lamp	Intact	Tail Lamps	Intact
Tyre Wheel	Average	Dash Board I Panel	Intact

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	CNG FITTED
----------------------------	-----	----------	------------



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



*Arvind Gaur*  
Arvind Gaur  
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)