



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3238

Date: 22-11-2025

## PRE -INSPECTION REPORT- FOUR WHEELER

|                            |                                  |
|----------------------------|----------------------------------|
| Insurer Details:           | THE NEW INDIA ASSURANCE CO. LTD. |
| Name of Proposer:          | MR AJAY SINGH CHOUHAN            |
| Date & Time of Inspection: | 22/11/2025 AT 02:11 PM           |
| Location of Vehicle:       | MORIJA, JAIPUR                   |

### Vehicle Particulars:

|                        |                        |             |           |
|------------------------|------------------------|-------------|-----------|
| Vehicle Regd No:       | RJ56 UA 0013           | Chassis No: | J40119    |
| Make/Model:            | MAHINDRA BOLERO<br>NEO | Engine No:  | J66183    |
| Date of Regd/Purchase: | 01/11/2021             | Mileage:    | 101962 KM |

### Inspection/Parts Details:

|                  |         |                    |         |
|------------------|---------|--------------------|---------|
| Roof             | Intact  | Bonnet             | Intact  |
| Lh Fender        | Dent    | Rh Fender          | Intact  |
| Lh Frt Door      | Intact  | Rh Frt Door        | Intact  |
| Lh Rear Door     | Intact  | Rh Rear Door       | Intact  |
| Lh Qtr Panel     | Intact  | Rh Qtr Panel       | Intact  |
| Lh Side Body     | Intact  | Rh Side Body       | Intact  |
| Lh Running Board | Intact  | Rh Running Board   | Intact  |
| Dicky            | Intact  | Front Bumper       | Scratch |
| Rear Bumper      | Intact  | Frt Ws Glass       | Intact  |
| Dicky Glass      | Intact  | Lh Mirror          | Intact  |
| Rh Mirror        | Intact  | Lh Head Lamp       | Intact  |
| Rh Head Lamp     | Intact  | Tail Lamps         | Intact  |
| Tyre Wheel       | Average | Dash Board I Panel | Intact  |

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

|                            |     |          |             |
|----------------------------|-----|----------|-------------|
| Recommended For Insurance: | Yes | Remarks: | RC VERIFIED |
|----------------------------|-----|----------|-------------|



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor


Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



*Arvind Gaur*  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)