



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3305

Date: 27-11-2025

PRE -INSPECTION REPORT- TWO WHEELER

Insurer Details:	UNITED INDIA INSURANCE CO. LTD
Name of Proposer:	AKASH MEENA
Date & Time of Inspection:	27/11/2025 AT 12:01 PM
Location of Vehicle:	JAIPUR

Vehicle Particulars:

Vehicle Regd No:	RJ14 KV 7010	Chassis No:	31489
Make/Model:	YAMAHA R15	Engine No:	00924
Date of Regd/Purchase:	22/06/2022	Mileage:	30998 KM

Inspection/Parts Details:

Frt Mud Guard	Intact	Fork	Intact
Handle	Intact	Speedometer	Intact
Fuel Tank	Intact	Rear Mud Guard	Intact
Silencer	Intact	Crank Case	Intact
Seats	Intact	Leg Guard	Intact
Front Wheel Rim	Intact	Rear Wheel Rim	Intact
Head Lamp	Intact	Tail Lamp	Intact
Front Visor Cowl	Intact	Front Rh Indicator	Intact
Front Lh Indicator	Intact	Rear Rh Indicator	Intact
Rear Lh Indicator	Intact	Rh Side Cover	Intact
Lh Side Cover	Intact	Clutch Lever	Intact
Brake Lever	Intact	Tyre	Average
Lh Mirror	Intact	Rh Mirror	Intact

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--




Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Arvind Gaur
Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)