



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3363

Date: 01-12-2025

PRE -INSPECTION REPORT- TWO WHEELER

| | |
|----------------------------|--------------------------------|
| Insurer Details: | UNITED INDIA INSURANCE CO. LTD |
| Name of Proposer: | ABHISHEK TILAWAT |
| Date & Time of Inspection: | 01/12/2025 AT 12:31 PM |
| Location of Vehicle: | JALUPURA JAIPUR |

Vehicle Particulars:

| | | | |
|------------------------|--------------|-------------|---------|
| Vehicle Regd No: | RJ60 SB 7526 | Chassis No: | 13502 |
| Make/Model: | YAMAHA MT 15 | Engine No: | 36961 |
| Date of Regd/Purchase: | 19/08/2023 | Mileage: | 9880 KM |

Inspection/Parts Details:

| | | | |
|--------------------|--------|--------------------|---------|
| Frt Mud Guard | Intact | Fork | Intact |
| Handle | Intact | Speedometer | Intact |
| Fuel Tank | Intact | Rear Mud Guard | Intact |
| Silencer | Intact | Crank Case | Intact |
| Seats | Intact | Leg Guard | Intact |
| Front Wheel Rim | Intact | Rear Wheel Rim | Intact |
| Head Lamp | Intact | Tail Lamp | Intact |
| Front Visor Cowl | Intact | Front Rh Indicator | Intact |
| Front Lh Indicator | Intact | Rear Rh Indicator | Intact |
| Rear Lh Indicator | Intact | Rh Side Cover | Intact |
| Lh Side Cover | Intact | Clutch Lever | Intact |
| Brake Lever | Intact | Tyre | Average |
| Lh Mirror | Intact | Rh Mirror | Intact |

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: | |
|----------------------------|-----|----------|--|



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor


Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur


Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)




Captured by Timestamp Camera
#Timestamp Camera
01/12/2025 12:30 PM GMT+05:30
Jalupura, Jaipur, Rajasthan, India,
26.92124°N, 75.81492°E
Timestamp camera



Captured by Timestamp Camera
#Timestamp Camera
01/12/2025 12:31 PM GMT+05:30
Jalupura, Jaipur, Rajasthan, India,
26.92127°N, 75.81493°E
Timestamp camera



Captured by Timestamp Camera
#Timestamp Camera
01/12/2025 12:22 PM GMT+05:30
Jalupura, Jaipur, Rajasthan, India,
26.92127°N, 75.81495°E
Timestamp camera



Captured by Timestamp Camera
#Timestamp Camera
01/12/2025 12:22 PM GMT+05:30
Jalupura, Jaipur, Rajasthan, India,
26.92128°N, 75.81493°E
Timestamp camera



Captured by Timestamp Camera
#Timestamp Camera
01/12/2025 12:23 PM GMT+05:30
Jalupura, Jaipur, Rajasthan, India,
26.92128°N, 75.81494°E
Timestamp camera



Captured by Timestamp Camera
#Timestamp Camera
01/12/2025 12:23 PM GMT+05:30
Jalupura, Jaipur, Rajasthan, India,
26.92126°N, 75.81493°E
Timestamp camera



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory