



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3402

Date: 02-12-2025

PRE -INSPECTION REPORT- FOUR WHEELER

Insurer Details:	THE NEW INDIA ASSURANCE COMPANY LTD
Name of Proposer:	KALU RAM BAIRWA
Date & Time of Inspection:	02/12/2025 AT 03:39 PM
Location of Vehicle:	BEAWAR

Vehicle Particulars:

Vehicle Regd No:	RJ51 CA 2410	Chassis No:	93461
Make/Model:	MARUTI ALTO 800 LXI	Engine No:	49968
Date of Regd/Purchase:	06/10/2018	Mileage:	99018 KM

Inspection/Parts Details:

Roof	Intact	Bonnet	Intact
Lh Fender	Dent	Rh Fender	Intact
Lh Frt Door	Intact	Rh Frt Door	Intact
Lh Rear Door	Dent	Rh Rear Door	Intact
Lh Qtr Panel	Intact	Rh Qtr Panel	Dent
Lh Side Body	Intact	Rh Side Body	Intact
Lh Running Board	Intact	Rh Running Board	Intact
Dicky	Intact	Front Bumper	Intact
Rear Bumper	Intact	Frt Ws Glass	Intact
Dicky Glass	Intact	Lh Mirror	Intact
Rh Mirror	Intact	Lh Head Lamp	Intact
Rh Head Lamp	Intact	Tail Lamps	Intact
Tyre Wheel	Average	Dash Board I Panel	Intact

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--




Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Dec 2, 2025 15:39:20
ब्यावर - मसूदा- बान्दरवाडा मार्ग
Bandanwara
Ajmer Division
Rajasthan



Dec 2, 2025 15:38:46
ब्यावर - मसूदा- बान्दरवाडा मार्ग
Bandanwara
Ajmer Division
Rajasthan



Dec 2, 2025 15:38:58
ब्यावर - मसूदा- बान्दरवाडा मार्ग
Bandanwara
Ajmer Division
Rajasthan



Dec 2, 2025 15:38:36
ब्यावर - मसूदा- बान्दरवाडा मार्ग
Bandanwara
Ajmer Division
Rajasthan



Dec 2, 2025 15:38:23
ब्यावर - मसूदा- बान्दरवाडा मार्ग
Bandanwara
Ajmer Division
Rajasthan



Dec 2, 2025 15:37:02
Bandanwara
Ajmer Division
Rajasthan




Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)