



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3432

Date: 03-12-2025

PRE -INSPECTION REPORT- FOUR WHEELER

Insurer Details:	THE NEW INDIA ASSURANCE COMPANY LTD
Name of Proposer:	MR. SAGAR JAISWAL
Date & Time of Inspection:	03/12/2025 AT 04:40 PM
Location of Vehicle:	DANGIYAWAS JODHPUR

Vehicle Particulars:

Vehicle Regd No:	UP52 BS 2098	Chassis No:	14033
Make/Model:	MAHINDRA SCORPIO S11	Engine No:	59427
Date of Regd/Purchase:	21/10/2022	Mileage:	72495 KM

Inspection/Parts Details:

Roof	Intact	Bonnet	Intact
Lh Fender	Intact	Rh Fender	Intact
Lh Frt Door	Intact	Rh Frt Door	Intact
Lh Rear Door	Intact	Rh Rear Door	Intact
Lh Qtr Panel	Intact	Rh Qtr Panel	Intact
Lh Side Body	Intact	Rh Side Body	Intact
Lh Running Board	Intact	Rh Running Board	Intact
Dicky	Intact	Front Bumper	Intact
Rear Bumper	Intact	Frt Ws Glass	Intact
Dicky Glass	Intact	Lh Mirror	Intact
Rh Mirror	Intact	Lh Head Lamp	Intact
Rh Head Lamp	Intact	Tail Lamps	Intact
Tyre Wheel	Average	Dash Board I Panel	Intact

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--




Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Arvind Gaur
Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)