



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 3622

Date: 15-12-2025

PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

Insurer Details:	UNITED INDIA INSURANCE COMPANY LTD
Name of Proposer:	MR. KARANA
Date & Time of Inspection:	15/12/2025 AT 10:56 AM
Location of Vehicle:	

Vehicle Particulars:

Vehicle Regd No:	RJ14 RE 6033	Chassis No:	53039
Make/Model:	TAFE MF 1035 DI	Engine No:	60464
Date of Regd/Purchase:	25/02/2023	Mileage:	1713 KM

Inspection/Parts Details:

Roof	Intact	Bonnetfrt Show	Intact
Front Bumper	Intact	Lh Door	--None--
Rh Door	--None--	Lh Side Body	Intact
Rh Side Body	Intact	Lh Fender	Intact
Rh Fender	Intact	Lh Qtr Panel	--None--
Rh Qtr Panel	--None--	Frt Ws Glass	--None--
Lh Qtr Glass	--None--	Rh Qtr Glass	--None--
Lh Head Lamp	Intact	Rh Head Lamp	Intact
Lh Tail Lamp	Intact	Rh Tail Lamp	Intact
Tyres	Average	Wheel Rim	Intact
Rear View Mirror	--None--	Dash Boardlpanel	Intact
Frt Grille	Intact	Type Of Load Body	Open

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--




Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory


73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)




Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)