



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 4109

Date: 13-01-2026

## PRE -INSPECTION REPORT- FOUR WHEELER

|                            |                                     |
|----------------------------|-------------------------------------|
| Insurer Details:           | THE NEW INDIA ASSURANCE COMPANY LTD |
| Name of Proposer:          | MR. ANIL KUMAR MEENA                |
| Date & Time of Inspection: | 13/01/2026 AT 04:28 PM              |
| Location of Vehicle:       | DANTA                               |

### Vehicle Particulars:

|                        |                 |             |          |
|------------------------|-----------------|-------------|----------|
| Vehicle Regd No:       | RJ23 UC 6392    | Chassis No: | 40402    |
| Make/Model:            | MAHINDRA BOLERO | Engine No:  | 35094    |
| Date of Regd/Purchase: | 17/06/2021      | Mileage:    | 68335 KM |

### Inspection/Parts Details:

|                  |         |                    |        |
|------------------|---------|--------------------|--------|
| Roof             | Intact  | Bonnet             | Intact |
| Lh Fender        | Intact  | Rh Fender          | Intact |
| Lh Frt Door      | Intact  | Rh Frt Door        | Intact |
| Lh Rear Door     | Intact  | Rh Rear Door       | Intact |
| Lh Qtr Panel     | Intact  | Rh Qtr Panel       | Intact |
| Lh Side Body     | Intact  | Rh Side Body       | Intact |
| Lh Running Board | Intact  | Rh Running Board   | Intact |
| Dicky            | Intact  | Front Bumper       | Intact |
| Rear Bumper      | Intact  | Frt Ws Glass       | Intact |
| Dicky Glass      | Intact  | Lh Mirror          | Intact |
| Rh Mirror        | Intact  | Lh Head Lamp       | Intact |
| Rh Head Lamp     | Intact  | Tail Lamps         | Intact |
| Tyre Wheel       | Average | Dash Board I Panel | Intact |

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

|                            |     |          |  |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: |  |
|----------------------------|-----|----------|--|



  
Arvind Gaur  
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)




Jan 13, 2026 4:27:38 PM  
SH-8A Sikar - Danta Road  
Danta  
Jaipur Division  
Rajasthan



Jan 13, 2026 4:26:54 PM  
SH-8A Sikar - Danta Road  
Danta  
Jaipur Division  
Rajasthan



Jan 13, 2026 4:27:20 PM  
SH-8A Sikar - Danta Road  
Danta  
Jaipur Division  
Rajasthan



Jan 13, 2026 4:26:23 PM  
SH-8A Sikar - Danta Road  
Danta  
Jaipur Division  
Rajasthan



Jan 13, 2026 4:26:30 PM  
SH-8A Sikar - Danta Road  
Danta  
Jaipur Division  
Rajasthan



Jan 13, 2026 4:28:22 PM  
SH-8A Sikar - Danta Road  
Danta  
Jaipur Division  
Rajasthan



*Arvind Gaur*  
Arvind Gaur  
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)