



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 4151

Date: 17-01-2026

PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

| | |
|----------------------------|------------------------------------|
| Insurer Details: | UNITED INDIA INSURANCE COMPANY LTD |
| Name of Proposer: | MR. RANG LAL MEENA |
| Date & Time of Inspection: | 17/01/2026 AT 12:40 PM |
| Location of Vehicle: | DYODA DOONGAR |

Vehicle Particulars:

| | | | |
|------------------------|-----------------|-------------|---------|
| Vehicle Regd No: | RJ14 RD 4491 | Chassis No: | 36724 |
| Make/Model: | TAFE MF 1035 DI | Engine No: | 20558 |
| Date of Regd/Purchase: | 19/04/2019 | Mileage: | 5630 KM |

Inspection/Parts Details:

| | | | |
|------------------|----------|-------------------|----------|
| Roof | Intact | Bonnetfrt Show | Intact |
| Front Bumper | Intact | Lh Door | --None-- |
| Rh Door | --None-- | Lh Side Body | Intact |
| Rh Side Body | Intact | Lh Fender | Intact |
| Rh Fender | Intact | Lh Qtr Panel | --None-- |
| Rh Qtr Panel | --None-- | Frt Ws Glass | --None-- |
| Lh Qtr Glass | --None-- | Rh Qtr Glass | --None-- |
| Lh Head Lamp | Intact | Rh Head Lamp | Intact |
| Lh Tail Lamp | Intact | Rh Tail Lamp | Intact |
| Tyres | Average | Wheel Rim | Intact |
| Rear View Mirror | --None-- | Dash Boardlpanel | Intact |
| Frt Grille | Intact | Type Of Load Body | Open |

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: | |
|----------------------------|-----|----------|--|



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor


Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



17-Jan-2026 12:40:56 pm
Dyoda Doongar
choud
Rajasthan



17-Jan-2026 12:40:09 pm
Dyoda Doongar
choud
Rajasthan



17-Jan-2026 12:40:24 pm
Dyoda Doongar
choud
Rajasthan



17-Jan-2026 12:39:41 pm
Dyoda Doongar
choud
Rajasthan



17-Jan-2026 12:39:54 pm
Dyoda Doongar
choud
Rajasthan



17-Jan-2026 12:40:39 pm
Dyoda Doongar
choud
Rajasthan



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory