



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 4381

Date: 03-02-2026

## PRE -INSPECTION REPORT- FOUR WHEELER

|                            |                                    |
|----------------------------|------------------------------------|
| Insurer Details:           | UNITED INDIA INSURANCE COMPANY LTD |
| Name of Proposer:          | MR. KAILASH GURJAR                 |
| Date & Time of Inspection: | 03/020/2026 AT 12:43 PM            |
| Location of Vehicle:       | JAIPUR                             |

### Vehicle Particulars:

|                        |              |             |          |
|------------------------|--------------|-------------|----------|
| Vehicle Regd No:       | RJ45 CK 1839 | Chassis No: | 63611    |
| Make/Model:            | MARUTI EECO  | Engine No:  | 46494    |
| Date of Regd/Purchase: | 17/01/2020   | Mileage:    | 68377 KM |

### Inspection/Parts Details:

|                  |         |                    |        |
|------------------|---------|--------------------|--------|
| Roof             | Intact  | Bonnet             | Intact |
| Lh Fender        | Intact  | Rh Fender          | Intact |
| Lh Frt Door      | Intact  | Rh Frt Door        | Intact |
| Lh Rear Door     | Intact  | Rh Rear Door       | Intact |
| Lh Qtr Panel     | Intact  | Rh Qtr Panel       | Intact |
| Lh Side Body     | Intact  | Rh Side Body       | Intact |
| Lh Running Board | Intact  | Rh Running Board   | Intact |
| Dicky            | Intact  | Front Bumper       | Intact |
| Rear Bumper      | Intact  | Frt Ws Glass       | Intact |
| Dicky Glass      | Intact  | Lh Mirror          | Intact |
| Rh Mirror        | Intact  | Lh Head Lamp       | Intact |
| Rh Head Lamp     | Intact  | Tail Lamps         | Intact |
| Tyre Wheel       | Average | Dash Board I Panel | Intact |

**Note:** - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

|                            |     |          |  |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: |  |
|----------------------------|-----|----------|--|



[Click here to verify](#)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



# Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



3 फ़र० 2026 12:45:15 pm  
34 Manipal University Road  
Dahmi Kalan  
Jaipur Division  
Rajasthan



3 फ़र० 2026 12:44:21 pm  
मणिपाल युनिवर्सिटी मार्ग  
दहमी कलां  
जयपुर डिवीजन  
राजस्थान



3 फ़र० 2026 12:43:37 pm  
मणिपाल युनिवर्सिटी मार्ग  
दहमी कलां  
जयपुर डिवीजन  
राजस्थान



3 फ़र० 2026 12:43:05 pm  
मणिपाल युनिवर्सिटी मार्ग  
दहमी कलां  
जयपुर डिवीजन  
राजस्थान



3 फ़र० 2026 12:43:48 pm  
मणिपाल युनिवर्सिटी मार्ग  
दहमी कलां  
जयपुर डिवीजन  
राजस्थान



3 फ़र० 2026 12:44:05 pm  
मणिपाल युनिवर्सिटी मार्ग  
दहमी कलां  
जयपुर डिवीजन  
राजस्थान



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)

  
Arvind Gaur  
Surveyor & Loss Assessor

Authorized Signatory