



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 4687

Date: 23-02-2026

PRE -INSPECTION REPORT- TWO WHEELER

| | |
|----------------------------|------------------------------------|
| Insurer Details: | UNITED INDIA INSURANCE COMPANY LTD |
| Name of Proposer: | BHAGWATI PRASAD MEENA |
| Date & Time of Inspection: | 23/02/2026 AT 01:01 PM |
| Location of Vehicle: | SULTANPUR KOTA |

Vehicle Particulars:

| | | | |
|------------------------|------------------|-------------|-------------|
| Vehicle Regd No: | RJ20 ZS 7780 | Chassis No: | 22243 |
| Make/Model: | BAJAJ PULSAR 150 | Engine No: | 80849 |
| Date of Regd/Purchase: | 24/02/2021 | Mileage: | NOT WORKING |

Inspection/Parts Details:

| | | | |
|--------------------|--------|--------------------|---------|
| Frt Mud Guard | Intact | Fork | Intact |
| Handle | Intact | Speedometer | Intact |
| Fuel Tank | Intact | Rear Mud Guard | Intact |
| Silencer | Intact | Crank Case | Intact |
| Seats | Intact | Leg Guard | Intact |
| Front Wheel Rim | Intact | Rear Wheel Rim | Intact |
| Head Lamp | Intact | Tail Lamp | Intact |
| Front Visor Cowl | Intact | Front Rh Indicator | Intact |
| Front Lh Indicator | Intact | Rear Rh Indicator | Intact |
| Rear Lh Indicator | Intact | Rh Side Cover | Intact |
| Lh Side Cover | Intact | Clutch Lever | Intact |
| Brake Lever | Intact | Tyre | Average |
| Lh Mirror | Intact | Rh Mirror | Intact |

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

| | | | |
|----------------------------|-----|----------|--|
| Recommended For Insurance: | Yes | Remarks: | |
|----------------------------|-----|----------|--|



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Arvind Gaur
Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)