



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 5108

Date: 10-04-2026

PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

Insurer Details:	UNITED INDIA INSURANCE COMPANY LTD.
Name of Proposer:	MR. SHIV SHANKAR
Date & Time of Inspection:	10/04/2026 AT 08:20 AM
Location of Vehicle:	CHOMU

Vehicle Particulars:

Vehicle Regd No:	RJ41 RA 4290	Chassis No:	19963
Make/Model:	TAFE MF 241 DI	Engine No:	76691
Date of Regd/Purchase:	08/07/2021	Mileage:	3482 KM

Inspection/Parts Details:

Roof	Intact	Bonnetfrt Show	Intact
Front Bumper	Intact	Lh Door	--None--
Rh Door	--None--	Lh Side Body	Intact
Rh Side Body	Intact	Lh Fender	Intact
Rh Fender	Intact	Lh Qtr Panel	--None--
Rh Qtr Panel	--None--	Frt Ws Glass	--None--
Lh Qtr Glass	--None--	Rh Qtr Glass	--None--
Lh Head Lamp	Intact	Rh Head Lamp	Intact
Lh Tail Lamp	Intact	Rh Tail Lamp	Intact
Tyres	Average	Wheel Rim	Intact
Rear View Mirror	--None--	Dash Boardlpanel	Intact
Frt Grille	Intact	Type Of Load Body	Open

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	
----------------------------	-----	----------	--



[Click here to verify](#)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



Captured by Timestamp Camera
#Timestamp Camera
10/04/2026 10:30 AM GMT+05:30
Chomu, Rajasthan, India.
27.18379°N, 75.76058°E
Timestamp camera

Google



Captured by Timestamp Camera
#Timestamp Camera
10/04/2026 10:33 AM GMT+05:30
Chomu, Rajasthan, India.
27.18366°N, 75.76054°E
Timestamp camera

Google



Captured by Timestamp Camera
#Timestamp Camera
10/04/2026 10:23 AM GMT+05:30
Chomu, Rajasthan, India.
27.18364°N, 75.76053°E
Timestamp camera

Google



Captured by Timestamp Camera
#Timestamp Camera
10/04/2026 10:23 AM GMT+05:30
Chomu, Rajasthan, India.
27.18363°N, 75.76054°E
Timestamp camera

Google



Captured by Timestamp Camera
#Timestamp Camera
10/04/2026 10:24 AM GMT+05:30
Chomu, Rajasthan, India.
27.18365°N, 75.76053°E
Timestamp camera

Google



Captured by Timestamp Camera
#Timestamp Camera
10/04/2026 10:24 AM GMT+05:30
Chomu, Rajasthan, India.
27.18371°N, 75.76052°E
Timestamp camera

Google



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory