



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)

Ref No.: 5135

Date: 01-06-2026

PRE -INSPECTION REPORT- COMMERCIAL VEHICLE

Insurer Details:	NATIONAL INSURANCE CO. LTD.
Name of Proposer:	M/S JAI BALAJI TRADERS
Date & Time of Inspection:	01/06/2026 AT 01:15 PM
Location of Vehicle:	VILL-NAGAR, TEH-MALPURA, TONK

Vehicle Particulars:

Vehicle Regd No:	M/C SR NO-N730228	Chassis No:	SR NO-N730228
Make/Model:	KOMATSU EXCAVATOR	Engine No:	--
Date of Regd/Purchase:	31/01/2020	Mileage:	8538 HRS

Inspection/Parts Details:

Roof	Intact	Bonnetfrt Show	Scratch
Front Bumper	Intact	Lh Door	Intact
Rh Door	Intact	Lh Side Body	Intact
Rh Side Body	Intact	Lh Fender	--None--
Rh Fender	--None--	Lh Qtr Panel	--None--
Rh Qtr Panel	--None--	Frt Ws Glass	Broken
Lh Qtr Glass	--None--	Rh Qtr Glass	--None--
Lh Head Lamp	--None--	Rh Head Lamp	--None--
Lh Tail Lamp	--None--	Rh Tail Lamp	--None--
Tyres	--None--	Wheel Rim	--None--
Rear View Mirror	--None--	Dash Boardlpanel	Intact
Frt Grille	Intact	Type Of Load Body	Open

Note: - Pre Existing Damages are not covered in the Insurance. Kindly Co-relate with inspection photos. We confirm the observations cited above in respect of inspection/ verification of the vehicle.

Recommended For Insurance:	Yes	Remarks:	HYDRAULIC EXCAVATOR CONSISTING BOOM AND BUCKET, INVOICE NO- UDR/19-20/1277 DATED 31/01/2020
----------------------------	-----	----------	---------------------------------------------------------------------------------------------



Arvind Gaur
Surveyor & Loss Assessor

[Click here to verify](#)

Authorized Signatory

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)



Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory




Arvind Gaur

Surveyor & Loss Assessor (SLA / 65869 Valid up to 27-09-27)



[Click here to verify](#)

73-Sri Ram Nagar, Kalwar Road, Jhotwara, Jaipur, Ph- 9887147487, Mail ID- GAURSURVEYOR@YAHOO.CO.IN)


Arvind Gaur
Surveyor & Loss Assessor

Authorized Signatory